



INSPECTION REPORT

OCT 16 2002

SKINGSTON

565 cust\_id

202045 insp\_id

12387 site\_id

KENNELWOOD, INC.

Customer ID: 565

Certificate: 33-A-8388-

Site: 001

KENNELWOOD, INC.

Inspection

Type: ROUTINE INSPECTION

Date: SEP-03-2002

1913 N. STALEY ROAD  
CHAMPAIGN, IL 61821

3.1 (a)

3.1 (c)

HOUSING FACILITIES, GENERAL.

(a) Structure; construction. Housing facilities for dogs and cats must be designed and constructed so that they are structurally sound. They must be kept in good repair, and they must protect the animals from injury, contain the animals securely, and restrict other animals from entering.

\*\*\* Several of the entry doors in the kennel buildings have lost their seal, or the seals have come loose and there are large gaps between the frames and the doors. These gaps need to be sealed to help prevent vermin and rodent infestation in the buildings. In the third building from the south, rodents have been chewing on the interior walls of the building. Rodents and vermin can be disease vectors, and the animals must be protected from them. The rodents must be eliminated and the walls repaired so they may be readily cleaned and sanitized.

Correct by: November 8, 2002

(c) Surfaces--

(1) General requirements. The surfaces of housing facilities--including houses, pens, and other furniture-type fixtures and objects within the facility--must be constructed in a manner and made of materials that allow them to be readily cleaned and sanitized, or removed or replaced when worn or soiled. Interior surfaces and any surfaces that come in contact with dogs or cats must:

(i) Be free of excessive rust that prevents the required cleaning and sanitization, or that affects the structural strength of the surface; and

(ii) Be free of jagged edges or sharp points that might injure the animal...

\*\*\*Several of the dog resting platforms have large cracks on the tops that could easily pinch the dogs paws or skin. These cracks should be repaired or the platforms replaced.

Correct by: October 9, 2002

\*\*\*The water lines running in to the dog pens are coated with rust from water leaks. Rust makes it impossible to clean and sanitize adequately. These lines should be replaced or sealed in some way to ensure that they can be properly cleaned.

Prepared By:

*Susan Kingston*

SUSAN KINGSTON, D. V. M., USDA, APHIS, Animal Care

Title: VETERINARY MEDICAL OFFICER, Inspector ID: 1049

Received By: (b)(6), (b)(7)c

Title:

Date:

SEP-04-2002

Date:

SEP-04-2002



INSPECTION REPORT

OCT 16 2002

SKINGSTON

565 cust\_id

202045 insp\_id

12587 site\_id

Correct by: November 8, 2002

3.2 ( b )

3.2 ( d )

**INDOOR HOUSING FACILITIES.**

(b) Ventilation. Indoor housing facilities for dogs and cats must be sufficiently ventilated at all times when dogs or cats are present to provide for their health and well-being, and to minimize odors.

\*\*\*In the second building from the south, cats are being housed. Upon entering this building, the odor is immediately recognized and quite strong. More effort must be made to minimize this odor.

Correct by: October 9, 2002

(d) Interior surfaces. The floors and walls of indoor housing facilities, and any other surfaces in contact with the animals, must be impervious to moisture.

\*\*\*The buildings housing dogs have several areas where the paint is chipping and some areas are down to the cinder blocks. Surfaces must be impervious to moisture to allow proper cleaning.

Correct by: October 9, 2002

Prepared By:

*Susan Kingston*

SUSAN KINGSTON, D. V. M., USDA, APHIS, Animal Care

Title: VETERINARY MEDICAL OFFICER, Inspector ID: 1049

Received By: (b)(6), (b)(7)c

Title:

Date:

SEP-04-2002

Date:

SEP-04-2002